

**FITNESS CERTIFICATE**  
(To be filled by the inspecting Officer)  
(Assistant Engineer)

- |   |   |   |
|---|---|---|
| 1 | Name of the Officer   | :- Smt.PRIYAMMA PHILIP  |
| 2 | Name of School  | :- Sri.Raghavendra Vidyalaya  |
| 3 | Location with name of education District / Subdistrict  | :- S.L.puram,Cherthala  |
| 4 | Classification of building as specified in Column 4 of the application for fitness Certificate and size | :- 6.00x6.00x3.45m(12classrooms with verandah 1.80m width) RCC Structure                |
| 5 | Period of which the certificate is issued   | :- 2021 - 22  |
| 6 | Nature of defect if any   | :- Nil  |
|   | a. Foundation and basement  | :-  |
|   | b. Superstructure   | :-  |
|   | c. Doors and Windows  | :-  |
|   | d. Wood work wrought and put up   | :-  |
|   | e. Roof   | :- RCC  |
|   | f. Flooring   | :-  |
|   | g. Miscellaneous ( cracks etc.)   | :- Nil  |
| 7 | Any Major defects noticed which will render the Building unsafe in any manner                           | :- Nil  |
| 8 | Whether maintenance works have been done properly   | :- Yes  |
| 9 | Whether the structure is sound or not for conducting classes  | :- Yes, Structure is sound for conducting classes under normal wind & weather condition |

Note: 1) The stability of the structure should be examined also with reference to location, altitude intensity of wind exposure to flood etc.

2) Any additional observation it deemed necessary for the certificate may be furnished, separately with the certificate.

Certified that the School was inspected by me on 22.10.2021 and found to be fit to conduct classes for the period 2021 - 22 for the reasons stated above.

Place: Alappuzha  
Date :- 23.10.2021



*Priyama Philip*  
ASSISTANT ENGINEER  
LSGD Section, Mararikulam  
North Grama Panchayat